

One Cambridge Place, 50 Hampshire Street Cambridge, Massachusetts 02139 tel: 617 452-6000

fax: 617 452-8000

April 8, 2003

Assistant Attorney General I. Andrew Goldberg Environmental Protection Division 200 Portland Street Boston, Massachusetts 02114

Subject:

Brockton, Massachusetts

Wastewater Collection/Treatment Facility Consent Decree Civil Action No.88-3194

2003 - 1st Quarter Report

Dear Mr. Goldberg:

On behalf of the City of Brockton, we submit a quarterly report for your consideration regarding the City's Consent Decree Civil Action with the Commonwealth. This information is an update of the individual ongoing wastewater projects within the City.

Miscellaneous Sewer Pipe Repair and Replacement

The City has been performing minor sewer rehabilitation based upon the findings of the City Wide Sewer System Evaluation Survey (SSES). As a result of this work, several gallons of extraneous flow have been removed from the sewer system. The attached Table 1 is a summary of sewer system repairs documented by the Brockton Sewer Department.

2. Phase I Sewer System Rehabilitation

Based on the recommendations of the City Wide Sewer System Evaluation Survey, several phases of rehabilitation construction are required to reduce quantities of I/I. Phase I is a \$2,000,000 effort to replace sewer pipe and repair manholes. Local funding is being provided for the entire project since the city didn't receive consideration for State Revolving Loan Funds. During the 1st quarter of 2003, this project removed approximately 123,030gpd of infiltration from the Brockton sewer system.



Mr. Goldberg April 8, 2003 Page 2

# 3. Phase II Sewer System Rehabilitation

As part of FY03 budgeting, the City included another \$2,000,000 for the Phase II Sewer System Rehabilitation project. The design of this work is underway. This project is expected to eliminate significant sources of I/I.

# 4. Inflow Removal Program

The City has begun an aggressive private and public inflow removal program. This work includes the removal of sump pumps, roof leaders and other sources of extraneous flow that were identified during previous studies. The Department of Public Works is assisting property owners and other municipal departments with the procedures and solutions for removal of these illegal connections. Table 2 summarizes the inflow removed as part of this program. Since the inception of this program, approximately 2.4mgd of inflow has been removed from the collection system.

# 5. Pursuit of SRF Funds

DEP has listed Brockton eligible for funding as part of the SRF program. The FY03 Intended Use Plan identifies that \$20 million of the total \$59.7 million has been committed for treatment and sewer system improvements in Brockton. A portion of the \$20 million will be used to perform the Phase III Sewer System Rehabilitation project.

# 6. I/I Reduction by Whitman and Abington

Brockton continuous to negotiate with the Towns of Abington and Whitman regarding the reduction of extraneous flows tributary from their sewer systems. A summary of work performed by Abington during the 1st quarter has been enclosed and a summary from Whitman will be provided when the town completes the work.

We trust this information meets your expectations regarding the required progress report. Please feel free to contact me regarding any questions or comments on this information.



Mr. Goldberg April 8, 2003 Page 3

Very truly yours,

Gregory A. Roy, P.E.

Principal

Camp Dresser & McKee Inc.

cc: Thomas Plouffe, City Solicitor

J. Condon, Chief Financial Officer

Robert D. Smith, DPW Commissioner

Eric Hall, EPA

David DiLorenzo, Joseph Shepherd, MADEP, SER

Robert Cady, MADEP, Boston

Hugh Spurway, USF

Patrick D. Hughes, CDM

Table 1

# City of Brockton, Massachusetts

# Consent Decree, Civil Action No.88-3194

# Response to Item 22(2)

Date   Work Performed   Description of Work   Memowed   Removed			History of Sewer System Repair and Renabilitation		Flow in gallons	per day	
Description of Work   Removed   Removed   Removed   per quarter   Sum	Annual	Dates		Infiltration			Exfiltration
not completed no			Description of Work				Source
not completed not com	Quarter	WOIK FEITOTHICU	Description of work	Removed	Removed	per quarter	Bource
not completed completed not complet		not completed	002-079 MH rehab				
not completed not completed to consultate of the completed not completed to completed to completed to completed not completed to 10-00 MH rehab         5,760           not completed to 10-00 MH rehab         7,200           not completed to 10-10 MH rehab         5,760           not completed to 10-10 MH rehab         4,320           not completed to 10-10 MH rehab         2,880           not completed to 10-10 MH rehab         3,200           not completed to 10-10 MH rehab         7,200           not completed to 10-10 MH rehab         2,800           not completed to 10-10 MH rehab         2,160           not completed to 10-10 MH rehab         2,160           not completed to 10-10 MH rehab         2,280           not completed to 40-10 MH rehab         7,200           not completed to 10-10 MH rehab         7,200		not completed	002-081 MH rehab	2,880			
not completed not com		not completed	002-098 MH rehab	4,320			
not completed no		not completed	002-201 MH rehab	2,880			
not completed not completed not completed on the completed of the co			002-200A MH rehab	2,880			
not completed not com			004-006 MH rehab				
not completed not completed not completed not completed of 011-002 MH rehab         4,320           not completed not complete		•	009-017A MH rehab	7,200			
not completed 01-1002 MH rehab 2, 880 not completed 01-1018 MH rehab 2, 880 not completed 01-1018 MH rehab 2, 880 not completed 01-1018 MH rehab 2, 880 not completed 017-125 MH rehab 4, 320 not completed 017-125 MH rehab 4, 320 not completed 017-125 MH rehab 7, 200 not completed 025-041A MH rehab 28, 800 not completed 025-041A MH rehab 28, 800 not completed 031-058 MH rehab 3, 300 not completed 031-058 MH rehab 3, 300 not completed 031-058 MH rehab 3, 300 not completed 031-059 MH rehab 4, 320 not completed 032-019 MH rehab 4, 320 not completed 033-021 MH rehab 7, 200 not completed 034-079 MH rehab 7, 200 not completed 044-079 MH rehab 7, 200 not completed 045-033 MH rehab 7, 200 not completed 045-033 MH rehab 7, 200 not completed 045-033 MH rehab 7, 200 not completed 045-034 MH rehab 7, 200 not completed 046-013 MH rehab 7, 200 not completed 065-028 MH rehab 7, 200 not completed North Cary Steet 040-029 to 040-028 330 12° 11,530 not completed North Cary Steet 040-029 to 040-028 330 12° 11,530 not completed 8284 Ashiland Steet 040-018 to 040-028 130′ 12° 11,530 not completed 8284 Ashiland Steet 040-018 to 040-028 130′ 12° 11,530 not completed 8284 Ashiland Steet 040-018 to 040-019 330′ 12° 11,530 not completed 8284 Ashiland Steet 040-018 to 040-019 330′ 12° 11,530 not completed 8284 Ashiland Steet 040-01			011-001 MH rehab				
not completed on 10-10-18 MH rehab not completed on 10-20-07 MH rehab not completed not completed on 10-20-07 MH rehab not completed not completed not completed on 10-20-07 MH rehab not completed not completed on 10-20-07 MH rehab not completed not com		•	011-002 MH rehab	4,320			
not completed         012-067 MH rehab         2,160           not completed         017-125 MH rehab         4,320           not completed         017-054 MH rehab         7,200           not completed         02-1001 MH rehab         28,800           not completed         02-0401 MH rehab         4,320           not completed         027-068 MH rehab         2,160           not completed         031-106 MH rehab         2,880           not completed         031-106 MH rehab         7,200           not completed         031-106 MH rehab         7,200           not completed         031-080 MH rehab         7,200           not completed         032-019 MH rehab         4,320           not completed         033-020 MH rehab         7,200           not completed         041-079 MH rehab         7,200           not completed         045-065 MH rehab         7,200           not completed         045-065 MH rehab         7,200           not completed         046-013 MH rehab         2,160           not completed         048-0370 MH rehab         3,600           not completed         048-0370 MH rehab         3,600           not completed         065-028 MH rehab         3,600							
not completed         012-076 MH rehab         2,880           not completed         017-125 MH rehab         4,320           not completed         017-054 MH rehab         28,800           not completed         025-0414 MH rehab         4,320           not completed         025-0414 MH rehab         2,160           not completed         031-016 MH rehab         2,880           not completed         031-089 MH rehab         7,200           not completed         031-089 MH rehab         7,200           not completed         032-019 MH rehab         7,200           not completed         032-019 MH rehab         2,880           not completed         041-079 MH rehab         7,200           not completed         045-033 MH rehab         7,200           not completed         045-033 MH rehab         7,200           not completed         045-035 MH rehab         7,200           not completed         047-029 MH rehab         2,160           not completed         047-029 MH rehab         3,600           not completed         048-037 MH rehab         3,600           not completed         052-010 MH rehab         3,600           not completed         065-021 MH rehab         3,600							
not completed         017-125 MH rehab         4,320           not completed         017-054 MH rehab         28,800           not completed         021-001 MH rehab         4,320           not completed         025-041A MH rehab         4,320           not completed         037-068 MH rehab         2,160           not completed         031-016 MH rehab         2,880           not completed         031-016 MH rehab         7,200           not completed         031-019 MH rehab         4,320           not completed         032-019 MH rehab         4,320           not completed         032-019 MH rehab         4,320           not completed         041-079 MH rehab         7,200           not completed         045-033 MH rehab         7,200           not completed         045-033 MH rehab         7,200           not completed         045-033 MH rehab         2,160           not completed         046-013A MH rehab         2,160           not completed         047-029 MH rehab         3,600           not completed         048-037D MH rehab         3,600           not completed         065-021 MH rehab         3,600           not completed         065-021 MH rehab         3,600 <tr< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr<>							
not completed         017-054 MH rehab         7,200           not completed         021-001 MH rehab         28,800           not completed         022-068 MH rehab         2,160           not completed         031-068 MH rehab         2,880           not completed         031-089 MH rehab         7,200           not completed         031-080 MH rehab         7,200           not completed         032-019 MH rehab         4,320           not completed         033-021 MH rehab         2,880           not completed         041-079 MH rehab         7,200           not completed         045-033 MH rehab         7,200           not completed         045-033 MH rehab         7,200           not completed         045-035 MH rehab         7,200           not completed         045-039 MH rehab         2,160           not completed         045-099 MH rehab         2,160           not completed         047-099 MH rehab         2,160           not completed         049-091 MH rehab         2,160           not completed         052-010 MH rehab         3,600           not completed         055-010 MH rehab         3,600           not completed         065-028 MH rehab         31,680		•					
not completed         021-001 MH rehab         28,800           not completed         025-041A MH rehab         4,220           not completed         031-016 MH rehab         2,160           not completed         031-016 MH rehab         7,200           not completed         031-030 MH rehab         7,200           not completed         032-019 MH rehab         4,320           not completed         033-021 MH rehab         2,880           not completed         045-033 MH rehab         7,200           not completed         045-033 MH rehab         7,200           not completed         045-055 MH rehab         7,200           not completed         046-013A MH rehab         7,200           not completed         047-029 MH rehab         2,160           not completed         047-029 MH rehab         3,600           not completed         048-057D MH rehab         3,600           not completed         065-021 MH rehab         3,600           not completed         065-021 MH rehab         3,600           not completed         065-021 MH rehab         3,600           not completed         065-028 MH rehab         3,600           not completed         065-028 MH rehab         3,600 <tr< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr<>							
not completed not completed not completed of 27-068 MH rehab         2,160           not completed not completed not completed not completed of 31-106 MH rehab         2,880           not completed not c		*					
not completed not completed not completed or completed not comp							
not completed on comp		•					
not completed         031-089 MH rehab         7,200           not completed         031-050 A MH rehab         7,200           not completed         032-019 MH rehab         4,320           not completed         033-021 MH rehab         2,880           not completed         041-079 MH rehab         7,200           not completed         045-033 MH rehab         7,200           not completed         045-065 MH rehab         7,200           not completed         045-065 MH rehab         2,160           not completed         047-029 MH rehab         3,600           not completed         048-057D MH rehab         3,600           not completed         049-071 MH rehab         2,160           not completed         049-071 MH rehab         3,600           not completed         065-010 MH rehab         5,040           not completed         065-021 MH rehab         7,200           not completed         065-028 MH rehab         2,160           not completed         065-028 MH rehab         2,160           not completed         065-028 MH rehab         2,760           not completed         Woodland Avenue 035-107 to 035-107 264 '8"         69,120           not completed         North Cary Steet 040-031 to 040-029							
not completed         031-050A MH rehab         7,200           not completed         032-019 MH rehab         4,320           not completed         043-021 MH rehab         2,880           not completed         041-079 MH rehab         7,200           not completed         045-033 MH rehab         7,200           not completed         045-065 MH rehab         7,200           not completed         046-113A MH rehab         2,160           not completed         047-029 MH rehab         4,320           not completed         049-091 MH rehab         3,600           not completed         05-070 MH rehab         2,160           not completed         052-010 MH rehab         2,160           not completed         055-021 MH rehab         3,600           not completed         065-023 MH rehab         7,200           not completed         065-028 MH rehab         31,680           not completed         065-028 MH rehab         2,160           not completed         065-028 MH rehab         2,760           not completed         Woodland Avenue 035-107 to 035-106 391' 8"         2,760           not completed         Woodland Avenue 035-109 to 035-106 391' 8"         69,120           not completed         North Cary		•					
not completed         032-019 MH rehab         4,320           not completed         033-021 MH rehab         2,880           not completed         045-079 MH rehab         7,200           not completed         045-033 MH rehab         7,200           not completed         045-055 MH rehab         7,200           not completed         046-113A MH rehab         2,160           not completed         047-029 MH rehab         4,320           not completed         048-057D MH rehab         3,600           not completed         052-010 MH rehab         2,160           not completed         052-010 MH rehab         3,600           not completed         055-011 MH rehab         5,040           not completed         065-021 MH rehab         7,200           not completed         065-028 MH rehab         31,680           not completed         065-028 MH rehab         2,160           not completed         Woodland Avenue 035-107 to 035-106 391' 8"         2,760           not completed         Woodland Avenue 035-109 to 035-107 264' 8"         69,120           not completed         North Cary Steet 040-031 to 040-029 164' 12"         11,520           not completed         East Ashland Street 040-018 to 040-019 30' 12"         5,762							
not completed         033-021 MH rehab         2,880           not completed         041-079 MH rehab         7,200           not completed         045-033 MH rehab         7,200           not completed         045-065 MH rehab         7,200           not completed         046-113A MH rehab         2,160           not completed         047-029 MH rehab         3,600           not completed         048-057D MH rehab         2,160           not completed         049-091 MH rehab         3,600           not completed         061-011 MH rehab         3,600           not completed         061-011 MH rehab         3,600           not completed         065-021 MH rehab         7,200           not completed         065-028 MH rehab         31,680           not completed         065-028 MH rehab         2,160           not completed         065-008A MH rehab         2,160           not completed         Woodland Avenue 035-107 to 035-106 391' 8"         4,320           not completed         Woodland Avenue 035-109 to 035-107 264' 8"         69,120           not completed         North Cary Steet 040-031 to 040-028 180' 12"         11,520           not completed         East Ashland Street 040-018 to 040-017 203' 12"         5,762							
not completed       041-079 MH rehab       7,200         not completed       045-033 MH rehab       7,200         not completed       045-056 MH rehab       7,200         not completed       046-113A MH rehab       2,160         not completed       047-029 MH rehab       3,600         not completed       049-091 MH rehab       3,600         not completed       052-010 MH rehab       2,160         not completed       052-010 MH rehab       3,600         not completed       065-021 MH rehab       5,040         not completed       065-021 MH rehab       7,200         not completed       065-028 MH rehab       31,680         not completed       065-028 MH rehab       2,160         not completed       065-08A MH rehab       2,160         not completed       065-08A MH rehab       2,160         not completed       Woodland Avenue 035-107 to 035-106 391' 8"       2,760         not completed       Woodland Avenue 035-107 to 040-029 164' 12"       11,520         not completed       North Cary Steet 040-031 to 040-029 164' 12"       112,320         not completed       East Ashland Street 040-018 to 040-019 330' 12"       5,762         not completed       East Ashland Street 040-018 to 040-019 330' 12" <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>							
not completed       045-033 MH rehab       7,200         not completed       045-065 MH rehab       7,200         not completed       046-113A MH rehab       2,160         not completed       047-029 MH rehab       4,320         not completed       048-057D MH rehab       3,600         not completed       049-091 MH rehab       2,160         not completed       052-010 MH rehab       3,600         not completed       061-011 MH rehab       5,040         not completed       065-021 MH rehab       7,200         not completed       065-028 MH rehab       31,680         not completed       065-028 MH rehab       2,160         not completed       065-08A MH rehab       2,160         not completed       065-08A MH rehab       2,160         not completed       Woodland Avenue 035-107 to 035-106 391' 8"       2,760         not completed       Woodland Avenue 035-109 to 035-107 264' 8"       69,120         not completed       North Cary Steet 040-031 to 040-029 164' 12"       11,520         not completed       North Cary Steet 040-031 to 040-028 130' 12"       5,762         not completed       East Ashland Street 040-018 to 040-019 330' 12"       72,000         not completed       East Ashland Street 040							
not completed         045-065 MH rehab         7,200           not completed         046-113A MH rehab         2,160           not completed         047-029 MH rehab         4,320           not completed         048-057D MH rehab         3,600           not completed         049-091 MH rehab         2,160           not completed         052-010 MH rehab         3,600           not completed         061-011 MH rehab         5,040           not completed         065-021 MH rehab         7,200           not completed         065-028 MH rehab         31,680           not completed         065-08A MH rehab         2,160           not completed         065-008A MH rehab         4,320           not completed         060-008A MH rehab         2,760           not completed         Woodland Avenue 035-107 to 035-106 391' 8"         2,760           not completed         North Cary Steet 040-031 to 040-029 164' 12"         11,520           not completed         North Cary Steet 040-029 to 040-028 338' 12"         112,320           not completed         East Ashland Street 040-019 to 040-017 203' 12"         5,762           not completed         East Ashland Street 040-018 to 040-017 203' 12"         72,000				177. 18. 300.00000			
not completed       046-113A MH rehab       2,160         not completed       047-029 MH rehab       4,320         not completed       048-057D MH rehab       3,600         not completed       049-091 MH rehab       2,160         not completed       052-010 MH rehab       3,600         not completed       061-011 MH rehab       5,040         not completed       065-021 MH rehab       7,200         not completed       065-028 MH rehab       31,680         not completed       065-008A MH rehab       2,160         not completed       065-008A MH rehab       4,330         not completed       Woodland Avenue 035-107 to 035-106 391' 8"       2,760         not completed       Woodland Avenue 035-109 to 035-107 264' 8"       69,120         not completed       North Cary Steet 040-031 to 040-029 164' 12"       11,520         not completed       North Cary Steet 040-029 to 040-028 33' 12"       112,320         not completed       East Ashland Street 040-018 to 040-019 330' 12"       5,762         not completed       East Ashland Street 040-018 to 040-017 203' 12"       11,520							
not completed       047-029 MH rehab       4,320         not completed       048-057D MH rehab       3,600         not completed       049-091 MH rehab       2,160         not completed       052-010 MH rehab       3,600         not completed       061-011 MH rehab       5,040         not completed       065-021 MH rehab       7,200         not completed       065-028 MH rehab       31,680         not completed       065-08A MH rehab       2,160         not completed       065-08A MH rehab       4,320         not completed       Woodland Avenue 035-107 to 035-106 391' 8"       2,760         not completed       Woodland Avenue 035-109 to 035-107 264' 8"       69,120         not completed       North Cary Steet 040-031 to 040-029 130' 12"       11,520         not completed       North Cary Steet 040-029 to 040-028 338' 12"       112,320         not completed       East Ashland Street 040-018 to 040-019 330' 12"       5,762         not completed       East Ashland Street 040-018 to 040-019 330' 12"       72,000         not completed       East Ashland Street 040-018 to 040-019 20' 12''       11,520							
not completed       048-057D MH rehab       3,600         not completed       049-091 MH rehab       2,160         not completed       052-010 MH rehab       3,600         not completed       061-011 MH rehab       5,040         not completed       065-021 MH rehab       7,200         not completed       065-028 MH rehab       31,680         not completed       065-08A MH rehab       2,160         not completed       117-088A MH rehab       4,320         not completed       Woodland Avenue 035-107 to 035-106 391' 8"       2,760         not completed       Woodland Avenue 035-109 to 035-107 264' 8"       69,120         not completed       North Cary Steet 040-031 to 040-029 164' 12"       11,520         not completed       North Cary Steet 040-019 to 040-028 338' 12"       5,762         not completed       East Ashland Street 040-018 to 040-019 330' 12"       72,000         not completed       East Ashland Street 040-018 to 040-017 203' 12"       11,520		*					
not completed       049-091 MH rehab       2,160         not completed       052-010 MH rehab       3,600         not completed       061-011 MH rehab       5,040         not completed       065-021 MH rehab       7,200         not completed       065-028 MH rehab       31,680         not completed       065-028 MH rehab       2,160         not completed       065-08A MH rehab       2,160         not completed       Woodland Avenue 035-107 to 035-106 391' 8"       2,760         not completed       Woodland Avenue 035-109 to 035-107 264' 8"       69,120         not completed       North Cary Steet 040-031 to 040-029 164' 12"       11,520         not completed       North Cary Steet 040-029 to 040-028 338' 12"       112,320         not completed       East Ashland Street 040-019 to 040-028 130' 12"       5,762         not completed       East Ashland Street 040-018 to 040-019 330' 12"       72,000         not completed       East Ashland Street 040-018 to 040-017 203' 12"       11,520							
not completed       052-010 MH rehab       3,600         not completed       061-011 MH rehab       5,040         not completed       065-021 MH rehab       7,200         not completed       065-028 MH rehab       31,680         not completed       065-008A MH rehab       2,160         not completed       117-088A MH rehab       4,320         not completed       Woodland Avenue 035-107 to 035-106 391' 8"       2,760         not completed       Woodland Avenue 035-109 to 035-107 264' 8"       69,120         not completed       North Cary Steet 040-029 164' 12"       11,520         not completed       North Cary Steet 040-029 to 040-028 338' 12"       112,320         not completed       East Ashland Street 040-019 to 040-028 130' 12"       5,762         not completed       East Ashland Street 040-018 to 040-019 30' 12"       72,000         not completed       East Ashland Street 040-018 to 040-017 203' 12"       11,520							
not completed       061-011 MH rehab       5,040         not completed       065-021 MH rehab       7,200         not completed       065-028 MH rehab       31,680         not completed       065-008A MH rehab       2,160         not completed       117-088A MH rehab       4,320         not completed       Woodland Avenue 035-107 to 035-106 391' 8"       2,760         not completed       Woodland Avenue 035-109 to 035-107 264' 8"       69,120         not completed       North Cary Steet 040-031 to 040-029 164' 12"       11,520         not completed       North Cary Steet 040-019 to 040-028 338' 12"       112,320         not completed       East Ashland Street 040-019 to 040-028 130' 12"       5,762         not completed       East Ashland Street 040-018 to 040-019 330' 12"       72,000         not completed       East Ashland Street 040-018 to 040-017 203' 12"       11,520							
not completed 065-021 MH rehab 7,200 not completed 065-028 MH rehab 31,680 not completed 065-08A MH rehab 2,160 not completed 117-088A MH rehab 4,320 not completed Woodland Avenue 035-107 to 035-106 391' 8" 2,760 not completed Woodland Avenue 035-109 to 035-107 264' 8" 69,120 not completed North Cary Steet 040-029 10 040-029 164' 12" 11,520 not completed North Cary Steet 040-029 to 040-028 338' 12" 112,320 not completed East Ashland Street 040-019 to 040-028 130' 12" 5,762 not completed East Ashland Street 040-018 to 040-019 330' 12" 72,000 not completed East Ashland Street 040-018 to 040-017 203' 12" 11,520							
not completed       065-028 MH rehab       31,680         not completed       065-088 MH rehab       2,160         not completed       117-088A MH rehab       4,320         not completed       Woodland Avenue 035-107 to 035-106 391' 8"       2,760         not completed       Woodland Avenue 035-109 to 035-107 264' 8"       69,120         not completed       North Cary Steet 040-031 to 040-029 164' 12"       11,520         not completed       North Cary Steet 040-029 to 040-028 338' 12"       112,320         not completed       East Ashland Street 040-019 to 040-028 130' 12"       5,762         not completed       East Ashland Street 040-018 to 040-019 330' 12"       72,000         not completed       East Ashland Street 040-018 to 040-017 203' 12"       11,520							
not completed       065-008A MH rehab       2,160         not completed       117-088A MH rehab       4,320         not completed       Woodland Avenue 035-107 to 035-106 391' 8"       2,760         not completed       Woodland Avenue 035-109 to 035-107 264' 8"       69,120         not completed       North Cary Steet 040-031 to 040-029 164' 12"       11,520         not completed       North Cary Steet 040-029 to 040-028 338' 12"       112,320         not completed       East Ashland Street 040-019 to 040-019 330' 12"       5,762         not completed       East Ashland Street 040-018 to 040-019 330' 12"       72,000         not completed       East Ashland Street 040-018 to 040-017 203' 12"       11,520							
not completed 117-088A MH rehab 4,320 not completed Woodland Avenue 035-107 to 035-106 391' 8" 2,760 not completed Woodland Avenue 035-109 to 035-107 264' 8" 69,120 not completed North Cary Steet 040-031 to 040-029 164' 12" 11,520 not completed North Cary Steet 040-029 to 040-028 338' 12" 112,320 not completed East Ashland Street 040-019 to 040-028 130' 12" 5,762 not completed East Ashland Street 040-018 to 040-019 330' 12" 72,000 not completed East Ashland Street 040-018 to 040-017 203' 12" 11,520							
not completed       Woodland Avenue 035-107 to 035-106 391' 8"       2,760         not completed       Woodland Avenue 035-109 to 035-107 264' 8"       69,120         not completed       North Cary Steet 040-031 to 040-029 164' 12"       11,520         not completed       North Cary Steet 040-029 to 040-028 338' 12"       112,320         not completed       East Ashland Street 040-019 to 040-028 130' 12"       5,762         not completed       East Ashland Street 040-018 to 040-019 330' 12"       72,000         not completed       East Ashland Street 040-018 to 040-017 203' 12"       11,520							
not completed Woodland Avenue 035-109 to 035-107 264' 8" 69,120  not completed North Cary Steet 040-031 to 040-029 164' 12" 11,520  not completed North Cary Steet 040-029 to 040-028 338' 12" 112,320  not completed East Ashland Street 040-019 to 040-028 130' 12" 5,762  not completed East Ashland Street 040-018 to 040-019 330' 12" 72,000  not completed East Ashland Street 040-018 to 040-017 203' 12" 11,520		and the second s					
not completed North Cary Steet 040-031 to 040-029 164' 12" 11,520  not completed North Cary Steet 040-029 to 040-028 338' 12" 112,320  not completed East Ashland Street 040-019 to 040-028 130' 12" 5,762  not completed East Ashland Street 040-018 to 040-019 330' 12" 72,000  not completed East Ashland Street 040-018 to 040-017 203' 12" 11,520							
not completed       North Cary Steet 040-029 to 040-028 338' 12"       112,320         not completed       East Ashland Street 040-019 to 040-028 130' 12"       5,762         not completed       East Ashland Street 040-018 to 040-019 330' 12"       72,000         not completed       East Ashland Street 040-018 to 040-017 203' 12"       11,520		•					
not completed       East Ashland Street 040-019 to 040-028 130' 12"       5,762         not completed       East Ashland Street 040-018 to 040-019 330' 12"       72,000         not completed       East Ashland Street 040-018 to 040-017 203' 12"       11,520		the state of the s					
not completed East Ashland Street 040-018 to 040-019 330' 12" 72,000 not completed East Ashland Street 040-018 to 040-017 203' 12" 11,520							
not completed East Ashland Street 040-018 to 040-017 203' 12" 11,520							
11,020							
not completed Fact Ashland Street 040-017 to 040-016 252 12"		not completed	East Ashland Street 040-017 to 040-016 252' 12"				
not completed East Ashland Street 040-017 to 040-016 252' 12" 10,080		not completed	East risinand Street 0-70-017 to 0-70-010 232 12	10,080			

Annual	Dates			Flow in gallons	per day	
Quarter	Work Performed	Description of Work	Infiltration	Inflow	Total I/I	Exfiltratio
	not completed	East Ashland Street 040-016 to 040-015 24' 12"	Removed	Removed	per quarter	Source
	not completed	East Ashland Street 040-015 to 040-003B 154' 12"	8,640			
	not completed	Pleasant Street 008-011 to 008-010 61' 8"	6,480			
	not completed	Rockland Street 008-013 to 008-012 306' 8"	5,900			
	not completed	Belair Street 004-045 to 004-044 361' 8"	25,000			
	not completed	Belair Street 004-044 to 004-042 115' 8"	0			
	not completed	Belair Street 004-042 to 004-041 243' 8"	0			
	not completed	Belair Street 004-041 to 004-040 364' 8"	1,275			
	not completed	Belair Street 004-040 to 004-023 116' 10"	2,880			
	not completed	Belair Street 004-023 to 004-020, 248' 10"	3,600			
	not completed	Belair Street 004-020 to 004-016, 298' 10"	15,120			
	April 8, 2003	Belair Street 004-016 to 017-012A, 357' 10"	16,560			
	March 20, 2003	Belair Street 004-010 to 017-012A, 357 10"  Belair Street 017-012A to 017-011A 55' 10"	14,400			
Quarter 2003	March 10, 2003	Westgate Drive 007-127F to 007-127Q 196' 12"	0			
uar 003	February 26, 2003		34,560			
7 7	February 15, 2003	Easement off E. Westgate Dr. 007-127D to 007-127C 326' 12"	30,560			
181	February 10, 2003	Easement off E. Westgate Dr. 007-127C to 007-127B 251' 12"	57,500			
	December-02	Easement off E. Westgate Dr. 007-127B to 007-127 335' 12"	410		123,030 gpd	
2002	December-02	Belair Street 017-011A to 017-010B 174' 10"	26,640			
er	November-02	Belair Street 017-010B to 017-011B 98' 10"	11,520			
Quarter	November-02	Belair Street 017-011B to 017-010A 111' 10"	0			
Õ	November-02	Belair Street 017-010A to 017-009A, 280' 10"	2,160			
4th	October 3, 2002	Belair Street 017-009A to 017-001B 209' 10"	0			
		Disconnected private catch basins from city sewer at bank at 40 Legion Parkway see Photo 93A & 93B		107,000 gpd	147,320 gpd	
05	August 20, 2002	Removed catch basin grate on sewer manhole at end of Thatcher Crt. (MH 058-022)	100,000 gpd		, 81	
. 20	July 30, 2002	Ash St., replaced pipe and service from STA 1+22 to 1+56 (017-039 to 017-038) see Photo 92B	4,320 gpd			
rter	July 29, 2002	S. Fuller St., replaced pipe from STA 0+27 to 0+33 (018-016B to 018-016A) see Photo 90A & 90B	SPL			
na	July 27, 2002	Dover St., replaced service wye at STA 2+24 (018-017 to 018-016A) see Photo 87A & 87B	360 gpd			
3rd Quarter 2002	July 25, 2002	Dover St., replaced service wye at STA 2+40 (018-017 to 018-016A) see Photo 88A	1,440 gpd			
31	July 24, 2002	Forest Rd., replaced pipe from STA 0+17 to 0+23 (018-021A to 018-020A) see Photo 91A & 91B	SPL			
	July 23, 2002	Dover St., removed service wye at STA 2+18 (018-018B to 018-019C) see Photo 89A & 89B	SPL		106,120 gpd	

		History of Sewer System Repair and Renabilitation		Flow in gallons	per day	
Annual	Dates		Infiltration	Inflow	Total I/I	Exfiltration
Quarter	Work Performed	Description of Work	Removed	Removed	per quarter	Source
	May 28, 2002	Spring St., replaced pipe from STA 1+73 to 1+75 (017-038 to 017-037) see Photo 78A & 78B	SPL			
	May 21, 2002	Spring St., replaced service wye at STA 1+82 (017-037 to 017-036) see Photo 76A & 76B	4,320 gpd			
	May 20, 2002	Poplar Rd., replaced service wye at STA 0+60 (017-054 to 017-053) see Photo 77A & 77B	2,880 gpd			
	May 17, 2002	Poplar Rd., replaced service wye at STA 0+84 (017-055 to 017-054) see Photo 75A & 75B	720 gpd			
002	May 13, 2002	Poplar Rd., replaced service wye at STA 1+22 (017-055 to 017-054) see Photo 85A & 85B	1,440 gpd			
2nd Quarter 2002	May 9, 2002	Augusta Ave., replaced pipe from STA 1+08 to 1+12 (017-115 to 017-113) see Photo 84A & 84B	SPL			
ırte	May 8, 2002	Prospect Ave., replaced pipe from STA 0+23 to 0+27 (017-114 to 017-113) see Photo 83A & 83B	4,320 gpd			
Qu.s	May 8, 2002	Hancock Av., replaced pipe from STA 0+47 to 0+49 (009-086 to 009-085A) see Photo 74A & 74B	720 gpd			
p	May 7, 2002	Earle St., replaced pipe from STA 2+20 to 2+25 (017-013A to 017-011A) see Photo 82A & 82B	SPL			
7	May 7, 2002	Earle St., replaced pipe from STA 0+50 to 0+52 (017-013A to 017-011A) see Photo 79A & 79B	SPL			
	May 6, 2002	Elm St., replaced pipe from STA 0+02 to 0+06 (011-011A to 011-011) see Photo 86A & 86B	720 gpd			
	May 2, 2002	Sunset Dr., replaced pipe from STA 0+00 to 0+05 (011-016 to 011-015) see Photo 81A & 81B	2,880 gpd			
	May 1, 2002	Sunset Dr., replaced pipe from STA 2+72 to 2+77 (011-017 to 011-016) see Photo 80A & 80B	720 gpd		18,720 gpd	
	March 28, 2002	Hancock Ave., removed service stub at STA 1+45 (009-087 to 009-086) see Photo 73A & 73B	200 gpd	WITH THE RESERVE TO T	10,720 дра	
	March 21, 2002	Hancock Ave., replaced service sad at 574 1 + 45 (605 667 to 605 666) see Photo 72A & 72B	1,440 gpd			
	March 11, 2002	Sunset Dr., replaced pipe from STA 1+45 to 1+52 (009-028 to 009-027) see Photo 71A & 71B	2,880 gpd			
	March 6, 2002	Margery Rd., replaced pipe from STA 1+11 to 1+16 (009-024 to 009-025A) see Photo 65A & 65B	1,440 gpd			
02	March 5, 2002	Candy Ln., replaced pipe from STA 1+64 to 1+68 (009-024 to 009-020) see Photo 62A & 62B	100 gpd			
. 20	March 4, 2002	Candy Ln., replaced pipe from STA 0+26 to 0+51 (009-020 to 009-019) see Photo 67A & 67B	1,440 gpd			
1st Quarter 2002	February 28, 2002	Candy Ln., removed stub at STA 1+96 (009-021 to 009-020) see Photo 61A & 61B	SPL			
na	February 26, 2002	Candy Ln., replaced pipe from STA 1+58 to STA 1+64 (009-020 to 009-019) see Photo 63A & 63B	1,000 gpd			
st Q	February 25, 2002	N. Pearl St., replaced pipe from STA 0+15 to STA 0+25 (009-78A to 009-79) see Photo 70A & 70B	600 gpd			
==	February 21, 2002	Candy Ln., replaced pipe from STA 0+0 to STA 0+28 (009-021B to 009-021) see Photo 68A & 68B	200 gpd			
	February 20, 2002	Candy Ln., replaced pipe from STA 2+63 to STA 2+68 (009-021 to 009-020) see Photo 69A & 69B	360 gpd			
	February 20, 2002	Candy Ln., replaced pipe from STA 1+09 to STA 1+15 (009-021A to 009-021B) see Photo 64A & 64B	100 gpd			
	January 10, 2002	E. Westgate Dr., replaced pipe from STA 0+48 to STA 0+52 (007-127I to 007-127G) see Photo 66A & 66B	1,440 gpd		11,000 gpd	
	November 24, 2001	203 Prospect St., replaced broken service pipe at STA 0+10 (006-094 to 006-096)	SPL		11,000 gpu	
	November 19, 2001	Candy Lane, replaced pipe from STA 0+10 to 0+14 (009-041 to 009-040)	1,440 gpd			
001	November 15, 2001	Candy Ln., replaced pipe from STA 2+31 to 2+37 (009-043 to 009-043A) see Photo 59A & 59B	SPL			
r 20	November 14, 2001	Margery Rd., replaced pipe from STA 2+40 to 2+47 (009-042 to 009-041) see Photo 60A & 60B	SPL			
rte	November 13, 2001	Santee Road, replace pipe from STA 2+12 to 2+14 (009-058 to 009-056) see Photo 58A & 58B	SPL			
) na	November 13, 2001	Santee Road, replace pipe from STA 0+77 to 0+80 (009-058 to 009-056) see Photo 57A & 57B	SPL			
4th Quarter 2001	November 13, 2001	Santee Road, replace pipe from STA 0+50 to 0+53 (009-058 to 009-056) see Photo 56A & 56B	SPL			
4	October 17, 2001	191 Grove St., replaced broken pipe from approx. STA 0+40 to 0+46 (056+011 to 056+010)	SPL			
	October 9, 2001	West Street, replaced service wye at STA 0+30 (014-080 to 014-079) see Photo 55A	SPL		1,440 gpd	
	September 9, 2001	Fitzpatrick Cir, replaced pipe from STA 0+16 to 0+18 (005-104A to 005-104) see Photo 54B	SPL		1,110 804	
100	August 20, 2001	Fitzpatrick Cir, replaced service wye at STA 1+32 (005-100 to 005-102) see Photo 52A & 52B	720			
er 2	August 16, 2001	Fitzpatrick Cir, replaced service wye at STA 0+15 (005-098 to 005-099A) see Photo 48A & 48B	720			
arte	August 14, 2001	Fitzpatrick Cir, replaced service wye at STA 0+43 (005-104 to 005-102A) see Photo 53A & 53B	1,440			
m O	August 13, 2001	Fitzpatrick Cir, replaced wye & main from STA 1+12 to 1+20 (005-104A to 005-104) see Photo 49A & 49B	8,640			
3rd Quarter 2001	August 7, 2001	Sophia Ave., replaced pipe from STA 2+68 to 2+70 (005-104 to 005-136) see Photo 50A & 50B	SPL			
	August 3, 2001	Fitzpatrick Cir, replaced pipe from STA 2+38 to 2+46 (005-100 to 005-102) see Photo 51A & 51B	SPL		11,520 gpd	

				Flow in gallons	per day	
Annual	Dates		Infiltration	Inflow	Total I/I	Exfiltration
uarter	Work Performed	Description of Work	Removed	Removed	per quarter	Source
	June 12, 2001	Oak Ridge Dr., replaced pipe from STA 1+40 to 1+55 (004-084 to 004-080) see Photo 47A & 47B	4,680 gpd			
	May 22, 2001	Crickett Rd., replaced pipe from STA 0+49 to 0+53 (004-057A to 004-053) see Photo 44A & 44B	7,200 gpd			
	May 21, 2001	Crickett Rd., replaced pipe from STA 1+82 to 1+86 (004-057A to 004-053) see Photo 45A & 45B	SPL			
	May 15, 2001	Shaws Parking Lot, removed entire 24" pipe (028-038 to 028-039)	SPL			
	May 15, 2001	Shaws Parking Lot, replaced entire 8" pipe (028-039 to 038-039A)	SPL			
01	May 10, 2001	VFW off N. Quincy, repaired service pipe and wye see Photo 46A & 46B	100,000 gpd			
2nd Quarter 2001	May 5, 2001	57 Wilder St., house service connected directly to drain pipe was removed see Photo 43	-			X
rter	April 25, 2001	Berglund Ave., replaced pipe from STA 2+10 to 2+13 (004-021 to 004-020) see Photo 37A & 37B	SPL			
na	April 24, 2001	Berglund Ave., replaced pipe from STA 1+84 to 1+92 (004-021 to 004-020) see Photo 34A & 34B	SPL			
O p	April 23, 2001	Berglund Ave., replaced service wye at STA 2+35 (004-021 to 004-020) see Photo 36A & 36B	dripping			
2n	April 20, 2001	Benham St., replaced pipe from STA to ( ) see Photo 38A & 38B	???			
	April 19, 2001	Miller Ave., Replaced pipe from STA to ( ) see Photo 39A & 39B	???			
	April 12, 2001	Berglund Ave., replaced pipe from STA 1+71 to 1+74 (004-021 to 004-020) see Photo 35A & 35B	SPL			
	April 10, 2001	Thompson Ave., replaced pipe from STA 1+03 to 1+07 (004-017 to 004-016) see Photo 41A & 41B	SPL			
	April 9, 2001	Thompson Ave., replaced 6 " pipe from STA 0+38 to 0+44 (004-017 to 004-016) see Photo 42A & 42B	SPL			
	April 2, 2001	Reservoir Road, replaced service at wye at STA 0+74 (002-104 to 002-103) see Photo 40A & 40B	1,440 gpd		108,640 gpd	
	March 27, 2001	Belmont and Ash St., replaced 8" pipe from STA 0+10 to 0+15 (018-072 to 018-073) see Photo 31A & 31B	SPL			
	March 19, 2001	Coventry Cir., replaced pipe from STA 0+91 to 0+97 (004-039A to 004-039) see Photo 34A & 34B	SPL			
	March 16, 2001	Coventry Cir., replaced pipe from STA 1+49 to 1+54 (004-039B to 004-039A) see Photo 32A & 32B	SPL			
	March 1, 2001	Coventry Cir., replaced pipe from STA 0+37 to 0+42 (004-039A to 004-039) see Photo 33A & 33B	14,400 gpd			
10	February 27, 2001	Coventry Cir., replaced pipe from STA 0+70 to 0+76 (004-039B to 004-039A) see Photo 30A & 30B	SPL			
200	February 26, 2001	Coventry Cir., replaced service connection at STA 0+12 (004-039B to 004-039A) see Photo 26A & 26B	5,760 gpd			
1st Quarter 2001	February 20, 2001	Colonel Bell Dr., replaced pipe from STA 2+41 to 2+44 (004-007 to 004-006) see Photo 29A & 29B	2,880 gpd			
uar	February 12, 2001	Coventry Cir., replaced service connection at STA 1+44 (004-039A to 004-039) see Photo 27A & 27B	4,320 gpd			
ō	February 9, 2001	Coventry Cir., replaced pipe from STA 1+79 to 1+82 (004-039A to 004-039)) see Photo 28A & 28B	4,320 gpd			
181	January 30, 2001	Colonel Bell Dr., replaced service connection at STA 1+16 (004-036 to 004-024) see Photo 22A & 22B	4,320 gpd			
	January 29, 2001	Colonel Bell Dr., removed service wye at STA 1+04 (004-025 to 004-026) see Photo 21A & 21B	SPL			
	January 31, 2001	Colonel Bell Dr., removed service wye at STA 0+33 (004-008 to 004-007) see Photo 23A & 23B	SPL			
	January 23, 2001	Colonel Bell Dr., replaced pipe from STA 1+34 to 1+37 (004-025 to 004-026) see Photo 25A & 25B	SPL			
	January 9, 2001	Colonel Bell Dr., replaced pipe from STA 0+62 to 0+64 (004-004 to 004-003) see Photo 24A & 24B	2,160 gpd		38,160 gpd	
	Nov. 30, 20000	West Haven Dr., replaced service connection at STA 0+44 (001-029 to 001-028) see Photo 12A & 12B	720 gpd			
	Nov. 28, 20000	West Haven Dr., replaced 7' of 8 "pipe, STA 1+85 to 1+92 (001-029 to 001-028) see Photo 20A & 20B	47 gpd *			
00	Nov. 16, 20000	Elliot St., replaced 8' of broken pipe at house #184 (042-121 to 042-122) see Photo15A & 15B	2,880 gpd			
200	Nov. 14, 20000	Darren Dr., replaced pipe at leaking joint at STA 0+52 (001-028 to 001-026) see Photo 19A & 19B	SPL			
4th Quarter 2000	October 26, 2000	Darren Dr., replaced pipe at leaking joint at STA 0+89 (001-028 to 001-026) see Photo 17A & 17B	SPL			
uar	October 23, 2000	Darren Dr., replaced 3 ' of cracked pipe STA 1+65 (001-028 to 001-026) see Photo 18A & 18B	SPL			
0	October 17, 2000	Darren Dr., replaced 2' of broken pipe at STA 0+08 (001-028 to 001-026) see Photo 16A & 16B	SPL			
#	October 5, 2000	Perkins Ave., replaced wye at STA 2+96 (063-009B to 063-005) see Photo 13A & 13B	SPL			
	October 3, 2000	Perkins Ave., plugged service wye at STA 3+30 (063-009B to 063-005) see Photo 14A & 14B	SPL			
	Sept. 15, 2000	Fitzpatrick Circle replaced 7' of 8" VCP	SPL		3,647 gpd	

				Flow in gallons	per day	
Annual	Dates		Infiltration	Inflow	Total I/I	Exfiltratio
Quarter	Work Performed	Description of Work	Removed	Removed	per quarter	Source
	August 21, 2000	Vine St., replaced broken pipe and service STA 0+99 to 1+01 (037-093 TO 037-092) see Photo 8A & 8B	SPL			
	August 17, 2000	12 Orchard Ave., removed service connection at STA 0+79 (037-128 to 037-127) see Photo 9A & 9B	180 gpd			
	August 18, 2000	14 Orchard Ave., replaced service connection at STA 2+28 (037-128 to 037-127) see Photo 10A & 10B	SPL			
0	July 29, 2000	Van Cliff Ave., replaced service at STA 0+31 (032-059 to 032-052)	SPL			
3rd Quarter 2000	July 27, 2000	Paulin Ave., replaced service at STA 0+93 (065-070 to 065-069) see Photo 11A & 11B	720 gpd			
E.	July 26, 2000	Burril St., replaced service & broken pipe from STA 2+18 to STA 2+19 (048-051 to 048-050)	2,160 gpd			
art	July 19, 2000	Roan Crt., replaced service connections at STA 0+27 & 0+29 (019-041 to 019-040) see Photo 1a & 1b	SPL			
Õ	July 19, 2000	Roan Crt., replaced service connection at STA 0+61 (019-041 to 019-040) see Photo 2a & 2b	SPL			
3rd	July 18, 2000	Albany St., replaced leaking joints at STA 2+85 (001-019 to 001-018) see Photo 3a & 3b	2,880 gpd			
	July 13, 2000	Stubb Rd., replaced service connection at STA 0+39 (009-026 to 009-024) see Photo 5a & 5b	360 gpd			
	July 13, 2000	Stubb Rd., replaced service connection at STA 1+03 (009-026 to 009-024) see Photo 6a & 6b	360 gpd			
	July 12, 2000	Stubb Rd., replaced broken pipe from STA 0+18 to 0+20 (009-026 to 009-024) see Photo 7a & 7b	2,880 gpd			
	July 11, 2000	Windsor Cir., Replaced a service tap at STA 0+05 (031-092 to 031-091) see Photo 4A & 4B	28,800 gpd		38,340 gpd	
<u>_</u>	May 2000	Winnifred Road, service replacement at STA 1+32 (015-025 to 015-024)	360 gpd		30,340 дра	
Quarter 2000	May 2000	Fitzpatrick Avenue, replaced 300' of 8-in VC pipe that was defective (005-145A to MH 005-143)	2,010 gpd *			
20 20	April 13, 2000	Main Interceptor infiltration leak at Meadow Lane bridge crossing	45,000 gpd			
	?	Embassy Nursing Home had direct sewer connection to surface water			47,370 gpd	X
arter Quarter	December 1999	Howard Street Sewer Replacement, 4,460 ft Snell Place Sewer Replacement of 15 ft	29,882 gpd * 101 gpd *		0 gpd	
4th Quarter 1999			Tot gpd #		29,983 gpd	
<u>.</u>	July 1999	Country Club Lane Sewer Replacement of 400 ft	2,680 gpd *			
Quarter 1999	July 1999	Country Club Place Sewer Replacement of 400 ft	2,680 gpd *			
Out 15			OF-			
					5,360 gpd	
Quarter 1999	April 5, 1999	Bellaire St. MH 004-016 to 004-015 replaced 10' of 10" pipe between STA 1+83 & 1+89	67 gpd *		OI .	
	N 1.60 1005				67 gpd	
1st Quarter 1999	March 29, 1999	Bellaire St. MH 004-016 to 004-015 replaced 6' of 10"pipe & 1 service between STA 1+37 & 1+41	40 gpd *			
Quar 1999	March 22, 1999	Bellaire St. MH 017-010B to 017-010A replace 6' of 10" pipe starting @ STA 0+28	40 gpd *			
st (						
	September 1998	Warran & Vaith 60 ft west (Helmony)			80 gpd	
ter 8		Warren & Keith, 60 ft west (Holmgren project)	402 gpd *			
uar 199	September 1998 September 1998	Warren & W. Chestnut, 74 ft west (Holmgren project)	496 gpd *			
Quarter 1998	September 1998 September 1998	Warren & Calmar, 74 ft east (Holmgren project) Warren & Market to Copeland, 1,135 ft (Holmgren project)	496 gpd *			
	Deptember 1990	WALLEL OV WALKEL TO CODE (2001 L. 13) If (Holmgren project)	7,605 gpd *			

				Flow in gallons	per day	
Annual	Dates		Infiltration	Inflow	Total I/I	Exfiltrati
Quarter	Work Performed	Description of Work	Removed	Removed	per quarter	Source
1st, 2nd, 3rd Quarter 1998	1998	Ellsworth (cured in place lining) 522 linear feet (017-125 to 017-118)	3,497 gpd *			
1,3	January 1998	Disconnected CB connection to sewer at Stonehill College (at Duffy Academic Center)	41,200 gpd *			
2nd rter						
uan						
10					44,697 gpd	
<u>+</u>	December 1997	Warren & Clifton, north to Nilsson, 3,000 ft	20,100 gpd *			
th arte			-			
4th Quarter 1997						
					20,100 gpd	
5	August 1, 1997	137 Perkins Ave, broken sewer leaking into a broken drain below				X
3rd Quarter 1997	?	Sewer overflow disconnected at siphon on Bartlett St.				X
Ou Ou	?	Sewer overflow disconnected on the East Side Interceptor				X
	August 1, 1997	Matfield Woods Estates, possible infiltration from a force main crossing of a brook			0 gpd	X
er	April 1997	Sawtell Ave. Sewer Replacement of 300 ft with 8" PVC (between Glendale St. and Alden St.)	2,010 gpd *			
& 2 art 997	March 1997	Wilmington St. Sewer Replacement of 100 ft with 15" PVC	670 gpd *			
1st & 2nd Quarter 1997	January 27, 1997	150 Lisa Drive Replaced 8 ft of sewer with 8" PVC	54 gpd *			
		Market Street Sewer Replacement			2,734 gpd	
4th Quarter 1996	October 1996	Oak Green Apartments off Reservoir Street, disconnected a sewer MH from draining a surface water	900,000 gpd			
art 996	October 1996	Biscayne Street				
0 m 0		Disconnected this abandoned private street from the city				
		sewer because of several defects and constant I/I.	570,000 gpd		1,470,000 gpd	
-i	August 1996	Howard Street Bridge Reconstruction, replaced 150 ft under bridge with 12" DI	1,005 gpd *			
3rd Quarter 1996	August 1996	Terminal Place on Evans St., replaced 300 ft of sewer with 8"PVC	2,010 gpd *			
Ou Ou						
	1006	D 1 150 C W 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			3,015 gpd	
_ ter	May 1996	- Replaced 50 ft from Warren Ave. going west with 8" PVC	335 gpd *			
2nd arri 996	May 1996	- Replaced 250 ft from intersection of Copeland with 12" DI	1,675 gpd *			
2nd Quarter 1996	May 1996	- Replaced 240 ft from Warren Ave. going east with 24" PVC	1,608 gpd *			
	1/ 1/22 100/				3,618 gpd	
, ter	March 22, 1996	Augusta Ave. replaced 6 ft with 8" PVC	40 gpd *			
1st 1art 1996	February 29, 1996	Ash St. and Pleasant St. replaced 25 ft with 8" PVC	168 gpd *			
1st Quarter 1996						
	Dec. 27, 1995	60 Dalais Ch. real and 10 ft with 1011 DV/C			208 gpd	
s ter	Dec. 21, 1995	68 Belair St. replaced 18 ft with 10" PVC	121 gpd *			-
4th Quarter 1995						
0						
					121 gpd	

				Flow in gallons		
Annual	Dates		Infiltration	Inflow	Total I/I	Exfiltration
Quarter	Work Performed	Description of Work	Removed	Removed	per quarter	Source
	JanMay 1995	Howard Street Interceptor Project				
		- Replaced 838 ft on Intervale St. with 21" PVC	5,615 gpd *			
		- Replaced 244 ft on Dyer St. with 21" PVC	1,635 gpd *			
		- Replaced 1,511 ft on Winter St., Douglas St., and				
		Oscar Ave. with 18" PVC	10,124 gpd *			
	May 6, 1995	Rainville St. replaced 6 ft with 15" PVC	40 gpd *			
	April 1995	Sump pump removed at 55 Albert St.	8,640 gpd **			
	April 1995	Sump pump removed at 115/117 Ames St.	8,640 gpd **			
	April 1995	Sump pump removed at 234 Ames St.	8,640 gpd **			
	April 1995	Sump pump removed at 266 Ames St.	8,640 gpd **			
	April 1995	Sump pump removed at 60 Arthur St.	8,640 gpd **			
	April 1995	Sump pump removed at 122 Arthur St.	8,640 gpd **			
	April 1995	Sump pump removed at 21 Baltic Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 70 Baltic Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 185 Baltic Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 155 Alden St.	8,640 gpd **			
	April 1995	Sump pump removed at 116 Ames St.	8,640 gpd **			
	April 1995	Sump pump removed at 260 Ames St.	8,640 gpd **			
	April 1995	Sump pump removed at 292 Ames St.	8,640 gpd **			
	April 1995	Sump pump removed at 105 Arthur St.	8,640 gpd **			
	April 1995	Sump pump removed at 136 Arthur St.	8,640 gpd **			
	April 1995	Sump pump removed at 40 Baltic Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 77 Baltic Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 38 Banks St.	8,640 gpd **			
	April 1995	Sump pump removed at 65 Lawton Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 35 Louis St.	8,640 gpd **			
	April 1995	Sump pump removed at 22 Merton St.	8,640 gpd **			
	April 1995	Sump pump removed at 58 Merton St.				
	April 1995	Sump pump removed at 96 Merton St.	8,640 gpd **			
	April 1995	Sump pump removed at 116 North Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 175 Votal Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 154 North Ave.  Sump pump removed at 37 Saint Casimir St.	8,640 gpd **			
	April 1995	Sump pump removed at 37 Saint Casimir St.  Sump pump removed at 30 Louis St.	8,640 gpd **			
	April 1995		8,640 gpd **			
	April 1995	Sump pump removed at 29 Merton St.	8,640 gpd **			
	April 1995	Sump pump removed at 68 Merton St.	8,640 gpd **			
		Sump pump removed at 112 North Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 122 North Ave.	8,640 gpd **			
	April 1995 April 1995	Sump pump removed at 165 Ridge St. Sump pump removed at 24 Vermont Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 24 Vermont Ave.  Sump pump removed at 64 Banks St.	8,640 gpd **			
	April 1995	Sump pump removed at 11 Bellevue Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 124 Bellevue Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 42 Claremont St.	8,640 gpd **			
	April 1995	Sump pump removed at 45 Charchion St.  Sump pump removed at 107 Hovendon Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 107 Hovendon Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 113 Hovendon Ave.	8,640 gpd **			
	1775	comp pamp removed at 104 Hoveldon Ave.	8,640 gpd **			

#### History of Sewer System Repair and Rehabilitation

				Flow in gallons	per day	
Annual	Dates		Infiltration	Inflow	Total I/I	Exfiltration
Quarter	Work Performed	Description of Work	Removed	Removed	per quarter	Source
	April 1995	Sump pump removed at 247 Howard St.	8,640 gpd **			
	April 1995	Sump pump removed at 10 Intervale St.	8,640 gpd **			
	April 1995	Sump pump removed at 19 Westford St.	8,640 gpd **			
	April 1995	Sump pump removed at 91 Banks St.	8,640 gpd **			
	April 1995	Sump pump removed at 117 Bellevue Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 59 Bonney St.	8,640 gpd **			
	April 1995	Sump pump removed at 25 Granite St.	8,640 gpd **			
	April 1995	Sump pump removed at 114 Hovendon Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 121 Hovendon Ave.	8,640 gpd **			
	April 1995	Sump pump removed at 243 Howard St.	8,640 gpd **			
	April 1995	Sump pump removed at 267 Howard St.	8,640 gpd **			
	April 1995	Sump pump removed at 15 Intervale St.	8,640 gpd **			
	April 11, 1995	240 Colonel Bell Drive replaced 6 ft with 8" PVC	40 gpd *			
	January 1, 1995	Sheridan St. replaced 10 ft with 10" PVC	67 gpd *			
	September 7, 1994	Braemoor Rd. replaced 8 ft with 8" PVC	54 gpd *			
	August 24, 1994	39 Southworth St. replaced 10 ft with 8" PVC	67 gpd *			
	August 1994	Fisk St. Sewer Replacement of 50 ft with 8" PVC	335 gpd *			
	June 6, 1994	Market St. replaced 200 ft with 10" PVC	1,340 gpd *			
	June 1994	I/I Rehabilitation Conducted by Atlantic Development Corporation				
		- Disconnected driveway drain from sewer at 28 Amark St.	4,320 gpd ***			
		- Disconnected driveway drain from sewer at 306 Field St.	4,320 gpd ***			
	Dec. 15, 1993	16 Hill St. replaced 8 ft with 8 PVC	54 gpd *			
	April 13, 1990	249 Boylston St. replaced 8 ft with 8" PVC	0 gpd *			
	May 1, 1990	Pleasant St. at Belair St. replaced 18 ft with 10" PVC	121 gpd *			

Estimated Total I/I Removed: 3,220,438 gpd

SPL: signs of previous leakage

<sup>\*</sup> I/I estimate based on average I/I rate of 6.7 gpd/ft. \*\* I/I estimate based on pump rate of 6 gpm.

<sup>\*\*\*</sup> I/I estimate based on pump rate of 3 gpm.

Table 2

# Brockton Inflow Removal Program Summary of Inspections, Repairs, and Potential Inflow Removal to Date 3/31/2003

<sup>\*</sup>Property inspections scheduled to resume 4/8/03

PRIVATE PROPERTIES		
Properties Inspected	174	
Properties with no illegal connections	50	
Properties with corrective work pending	9	
Properties with non-inflow related repairs complete	3	
Properties with inflow related repairs complete	112	
Potential gallons of daily inflow removed (gpd)	2,421,180	
NOTE - Quantity to date matches report dated 1/31/03. Two illegal connections", and one property with repaired cleanout		

Properties Inspected  Properties with no illegal connections	30
Properties with no illegal connections	
	26
roperties requiring corrective work	4 (Schools, Fire Sta No.1)

College Colleg

PARTIES THE SECOND STREET SECOND SECO

March 21, 2003

To: Jim Howell, Supt.

From: Mike Donovan, Foreman

RE: I&I 2003 first quarter report

CC: Greg Roy, CDM

Dear Jim,

The following I&I work was performed between January 1st and March 21, 2003.

- > Sent out letters regarding sump pumps to 3205 residents.
- > Put sump pump notice on local access cable channel.
- > Installed new pump controller at Hancock St. pump station that will monitor flow.
- Monitored all manholes that have been identified with wet conditions or possible leaks.
- > Inspected 329 manholes in areas of high ground water tables.
- > Servern Trent repaired (groute & sealed) 12 manholes, which may remove approximately 50,000 to 75,000 gallons per day infiltration.

Future I&I work will include the following;

- > Follow up on sump pump/excess wastewater remediation program.
- > Removal of sump pumps.
- > Replacing ductile iron castings with new cast iron castings.
- > Continue monitoring the collection system.

Thank you,

Mike Donovan Foreman